

JUN 1 2 1998

Indianapolis Division 6964 Hillsdale Ct. Indianapolis, IN 46250 Tel: (317) 842-4261 Fax: (317) 842-4286

P.O. 208205

ANALYTICAL REPORT

Mr. Richard Tyler
MILBANK MANUFACTORING INC
1400 E. HAVENS ST.
KOKOMO, IN 56901-3188

06/05/1998

NET Job Number:

98.03593

Page 1 of 3

Enclosed are the Analytical Results for the following samples submitted to NET, Inc. Indianapolis Division for analysis:

Project Description: TWICE WEEKLY WASTEWATER

Sample Number Sample Description

OUTFALL 001

208906

Date Taken Date Received

05/29/1998

05/29/1998

National Environmental Testing, Inc. certifies that the analytical results contained herein apply only to the specific samples analyzed.

Reproduction of this analytical report is permitted only in its entirety.

Project Representative

Con Barrer



JUN 1 2 1998

Indianapolis Division 6964 Hillsdale Ct. Indianapolis, IN 46250 Tel: (317) 842-4261 Fax: (317) 842-4286

ANALYTICAL REPORT

Mr. Richard Tyler
MILBANK MANUFACTORING INC
1400 E. HAVENS ST.
KOKOMO, IN 56901-3188

06/05/1998

Job No.: 98.03593

Page 2 of 3

Date Received: 05/29/1998

Job Description: TWICE WEEKLY WASTEWATER

Sample Number / Sample I.D	• Talk tang planter in		Sample Date/	Analyst &	Reporting		
Parameters	Result	Flag	Units	Date Analyzed	Method Limit		
				9.0			
208906 OUTFALL	001		05/29/1998				
Iron, ICP	<0.10		mg/L	tjg / 06/02/1998	EPA 200.7 <0.10		
Lead, ICP	<0.080		mg/L	tjg / 06/02/1998	EPA 200.7 <0.080		
Silver, ICP	<0.020		mg/L	tjg / 06/02/1998	EPA 200.7 <0.020		
Zinc, ICP	0.83		mg/L	tjg / 06/02/1998	EPA 200.7 <0.020		



Indianapolis Division 6964 Hillsdale Ct. Indianapolis, IN 46250 Tel: (317) 842-4261 Fax: (317) 842-4286

FIELD REPORT

JOB #: 98.03593

CLIENT: MILBANK MFG.

PROJECT: TWICE WEEKLY WASTEWATER

DATE: 5/29/98 SAMPLER(S): MTM

An ISCO model 6700 auto sampler was used in the composite mode of operation. The sampler was equipped with a plastic composite jug, tygon suction line, battery, ice, and strainer.

All reusable equipment is decontaminated with alconox, tap water, 5% nitric acid, and deionized water. New tygon suction tubing was used for the sampler. A stainless steel strainer was also used for the sampling event.

The sampler was set to take a sample every 30 minutes for 24 hours.

Monitoring start 08:00 on 5/28/98 Monitoring end 08:00 on 5/29/98

The composite sample was clear.

Notes: Samples were preserved, in the field, in the appropriate containers with any required preservative.



ENVIRONMENTAL TESTING, INC. COMPANY MILBANK MFG. ADDRESS JOD E. HAVENS ST. KOKOND, IN PHONE FAX PROJECT NAME/LOCATION TWICE WEEKLY WASTENDATOR PROJECT NUMBER PROJECT MANAGER ANALYSES SIGNATURE SIGNATURE											REPORT TO: KICHAR YLETR INVOICE TO: P.O. NO. NET QUOTE NO. To assist us in selecting the proper method Is this work being conducted for regulatory compliance monitoring? Yes No					
DATE TIME SAMPLE ID/DESCRIPTION 1998 . 1/23-5/29 OUTFALL OOL	₹ MATRIX	+	COMP	Т	and Ty Contain ONH	ners	ОТНЕЯ	METALS: F.	192		1		1,2,1			Is this work being conducted for regulatory enforcement action? Yes No Which regulations apply: RCRA NPDES Wastewater UST Drinking Water Other None COMMENTS
														Y		
SAMPLE REMAINDER DISPOSAL: RETURN SAMPLE RELINQUISHED BY: DATE TIME 129/98 /4:00 METHOD OF SHIPMENT	E REMAIND	E OF		VOL	ATILE	S FF	REE			CE2-				DATE 5/2		DATE RECEIVED FOR NET BY